









INSPECTION


May 11, 2021


I-40 Mississippi River Bridge is closed after a fracture was discovered in the tie girder (beam).















We spoke to media about the closure, inspections, and repair plans.




Safety First

We immediately started another inspection of the I-55 MS River Bridge.



Gather Information

We, TDOT, the FHWA, and contractors HNTB and Michael Baker assessed the damage.



INVESTIGATION

Earlier Evidence

Drone footage from a routine inspection of the cables in 2019.

Investigation and Review

- Requested US DOT Inspector General assign a special agent to investigate.
- FHWA reviewing our Bridge Inspection
 Process and Compliance.
- Asked TDOT to re-inspect and review our previous inspection of the I-55 MS River Bridge.
- Solicited consultants to review our Bridge Inspection Program.









Phase 1 Platform

Kiewit Infrastructure Group installed the temporary platform for Phase 1 Repairs.

May 22, 2021

Kiewit worked in shifts 24 hours a day on Phase 1 Repairs.

May 25, 2021

Kiewit completed Phase 1 Repairs.

Phase 2 Repairs

MAY 26

Design Finalized





"It's amazing what can be accomplished when you don't care who gets the credit."

- Harry S. Trumann

Bridge Inspection Program

- · Increase to Heavy Bridge Maintenance Budget
- · 2021 \$3.5 Million
- 2022 \$6.4 Million







State Highway Bridges


RENEW ARKANSAS HIGHWAYS PROGRAM


Est. \$1.1 Billion - 10 Year











Originally there was only a single lane for traffic traveling I-55 Southbound.

TDOT added a lane to the ramp at the Crump Interchange.

Their crews paved and restriped this section of the interchange over a weekend.

Improved Section

